Paints and varnishes - Methods of exposure to laboratory light sources - Part 1: General guidance (ISO e.

Ochologopala 16474-1:2013)



EESTI STANDARDI EESSÕNA

NATIONAL FOREWORD

See Eesti standard EVS-EN ISO 16474-1:2013	This Estonian standard EVS-EN ISO 16474-1:2013
sisaldab Euroopa standardi EN ISO 16474-1:2013	consists of the English text of the European standard
inglisekeelset teksti.	EN ISO 16474-1:2013.
Standard on jõustunud sellekohase teate avaldamisega EVS Teatajas.	This standard has been endorsed with a notification published in the official bulletin of the Estonian Centre for Standardisation.
Euroopa standardimisorganisatsioonid on teinud Euroopa standardi rahvuslikele liikmetele kättesaadavaks 20.11.2013.	Date of Availability of the European standard is 20.11.2013.
Standard on kättesaadav Eesti Standardikeskusest.	The standard is available from the Estonian Centre for Standardisation.

Tagasisidet standardi sisu kohta on võimalik edastada, kasutades EVS-i veebilehel asuvat tagasiside vormi või saates e-kirja meiliaadressile standardiosakond@evs.ee.

ICS 87.040

Standardite reprodutseerimise ja levitamise õigus kuulub Eesti Standardikeskusele

Andmete paljundamine, taastekitamine, kopeerimine, salvestamine elektroonsesse süsteemi või edastamine ükskõik millises vormis või millisel teel ilma Eesti Standardikeskuse kirjaliku loata on keelatud.

Kui Teil on küsimusi standardite autorikaitse kohta, võtke palun ühendust Eesti Standardikeskusega: Aru 10, 10317 Tallinn, Eesti; www.evs.ee; telefon 605 5050; e-post info@evs.ee

The right to reproduce and distribute standards belongs to the Estonian Centre for Standardisation

No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying, without a written permission from the Estonian Centre for Standardisation.

If you have any questions about copyright, please contact Estonian Centre for Standardisation: Aru 10, 10317 Tallinn, Estonia; www.evs.ee; phone 605 5050; e-mail info@evs.ee

EUROPEAN STANDARD NORME EUROPÉENNE EUROPÄISCHE NORM

EN ISO 16474-1

November 2013

ICS 87.040

Supersedes EN ISO 11341:2004, EN ISO 11507:2001

English Version

Paints and varnishes - Methods of exposure to laboratory light sources - Part 1: General guidance (ISO 16474-1:2013)

Peintures et vernis - Méthodes d'exposition à des sources lumineuses de laboratoire - Partie 1: Lignes directrices générales (ISO 16474-1:2013) Beschichtungsstoffe - Künstliches Bestrahlen oder Bewittern in Geräten - Teil 1: Allgemeine Anleitung (ISO 16474-1:2013)

This European Standard was approved by CEN on 26 October 2013.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN-CENELEC Management Centre or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the CEN-CENELEC Management Centre has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium, Bulgaria, Croatia, Cyprus, Czech Republic, Denmark, Estonia, Finland, Former Yugoslav Republic of Macedonia, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland, Turkey and United Kingdom.



EUROPEAN COMMITTEE FOR STANDARDIZATION COMITÉ EUROPÉEN DE NORMALISATION EUROPÄISCHES KOMITEE FÜR NORMUNG

CEN-CENELEC Management Centre: Avenue Marnix 17, B-1000 Brussels

Foreword

This document (EN ISO 16474-1:2013) has been prepared by Technical Committee ISO/TC 35 "Paints and varnishes" in collaboration with Technical Committee CEN/TC 139 "Paints and varnishes" the secretariat of which is held by DIN.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by May 2014, and conflicting national standards shall be withdrawn at the latest by May 2014.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. CEN [and/or CENELEC] shall not be held responsible for identifying any or all such patent rights.

This document supersedes EN ISO 11507:2001, EN ISO 11341:2004.

According to the CEN-CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Bulgaria, Croatia, Cyprus, Czech Republic, Denmark, Estonia, Finland, Former Yugoslav Republic of Macedonia, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland, Turkey and the United Kingdom.

Endorsement notice

The text of ISO 16474-1:2013 has been approved by CEN as EN ISO 16474-1:2013 without any modification.

Foreword Introduction 1 Scope 2 Normative references 3 Terms and definitions 4 Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources. 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure	
1 Scope 2 Normative references 3 Terms and definitions 4 Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device. 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions. 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	iv
1 Scope 2 Normative references 3 Terms and definitions 4 Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device. 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions. 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	v
Terms and definitions Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
Terms and definitions Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
4 Principle 4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
4.1 General 4.2 Significance 4.3 Use of accelerated tests with laboratory light sources 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
4.2 Significance 4.3 Use of accelerated tests with laboratory light sources 5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device. 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
5 Requirements for laboratory exposure devices 5.1 Irradiance 5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	2
5.1 Irradiance	4
5.2 Temperature 5.3 Humidity and wetting 5.4 Other requirements for the exposure device 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	4
5.3 Humidity and wetting 5.4 Other requirements for the exposure device. 6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
5.4 Other requirements for the exposure device. 6 Test specimens — Preparation, replicates, storage and conditioning. 6.1 Handling of test specimens. 6.2 Form, shape, preparation. 6.3 Number of test specimens. 6.4 Storage and conditioning. 7 Test conditions and procedure. 7.1 Set points for exposure conditions. 7.2 Property measurements on test specimens. 8 Periods of exposure and evaluation of test results. 8.1 General. 8.2 Sampling. 8.3 Determination of changes in properties after exposure. 8.4 Use of control materials.	
6 Test specimens — Preparation, replicates, storage and conditioning 6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
6.1 Handling of test specimens 6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
6.2 Form, shape, preparation 6.3 Number of test specimens 6.4 Storage and conditioning 7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	9
7 Test conditions and procedure 7.1 Set points for exposure conditions 7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	<u>9</u>
7.1 Set points for exposure conditions	
7.1 Set points for exposure conditions. 7.2 Property measurements on test specimens. 8 Periods of exposure and evaluation of test results. 8.1 General. 8.2 Sampling. 8.3 Determination of changes in properties after exposure. 8.4 Use of control materials.	
7.2 Property measurements on test specimens 8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
8 Periods of exposure and evaluation of test results 8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
8.1 General 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials	
 8.2 Sampling 8.3 Determination of changes in properties after exposure 8.4 Use of control materials 	
8.3 Determination of changes in properties after exposure	
8.4 Use of control materials	
	12
8.5 Use of results in specifications	
9 Test report	
Annex A (informative) Procedure for measuring the irradiance uniformity in the specesore area	
Annex B (informative) Factors that decrease the degree of correlation between artific accelerated weathering or artificial accelerated irradiation exposures and accuse exposures	tual-
Annex C (informative) Solar spectral irradiance standard	
Bibliography	

Introduction

Coatings from paints, varnishes and similar materials are often used outdoors or in indoor locations where they are exposed to solar radiation or to solar radiation behind glass for long periods. It is therefore very important to determine the effects of solar radiation, heat, moisture and other climatic stresses on the colour and other properties of polymers. Outdoor exposures to solar radiation and to solar radiation filtered by window glass are described in ISO 2810[9]. However, it is often necessary to determine more rapidly the effects of light, heat and moisture on the physical, chemical and optical properties of coatings with artificial accelerated weathering or artificial accelerated irradiation exposures that use specific laboratory light sources. Exposures in these laboratory devices are conducted under more controlled conditions than found in natural environments and are intended to accelerate polymer degradation and product failures. Relating results from accelerated weathering or artificial accelerated irradiation exposures to those obtained in actual-use conditions is difficult because of variability in both types of exposure and because laboratory tests often do not reproduce all the exposure stresses experienced by coatings exposed in actual-use conditions. In addition, the increase in rate of degradation by the accelerated test compared with natural exposure conditions varies with the type of material and its formulation. No single laboratory exposure test can be specified as a total simulation of actual-use exposures. The relative durability of materials in actual-use exposures can be very different depending on the location of the exposure because of differences in solar radiation, time of wetness, temperature, pollutants and other factors. Therefore, even if results from specific accelerated weathering or artificial accelerated irradiation exposures are found to be useful for comparing the relative durability of materials exposed in a particular outdoor location or in particular actual-use conditions, it cannot be assumed that they will be useful for determining the relative durability of materials exposed in a different outdoor location or in different actual-use conditions.

Paints and varnishes — Methods of exposure to laboratory light sources —

Part 1:

General guidance

1 Scope

- **1.1** This part of ISO 16474 provides information and general guidance relevant to the selection and operation of the methods of exposure described in detail in subsequent parts. It also describes general performance requirements for devices used for exposing paints and varnishes to laboratory light sources. Information about such performance requirements is provided for producers of artificial accelerated weathering or artificial accelerated irradiation devices.
- **1.2** This part of ISO 16474 also provides information on the interpretation of data from artificial accelerated weathering or artificial accelerated irradiation exposures.

2 Normative references

The following documents, in whole or in part, are normatively referenced in this document and are indispensable for its application. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 1513, Paints and varnishes — Examination and preparation of test samples

ISO 1514, Paints and varnishes — Standard panels for testing

ISO 2808, Paints and varnishes — Determination of film thickness

ISO 3270, Paints and varnishes and their raw materials — Temperatures and humidities for conditioning and testing

ISO 4618, Paints and varnishes — Terms and definitions

ISO 9370, Plastics — Instrumental determination of radiant exposure in weathering tests — General guidance and basic test method

ISO 15528, Paints, varnishes and raw materials for paints and varnishes — Sampling

ISO 16474-2, Paints and varnishes — Methods of exposure to laboratory light sources — Part 2: Xenon-arc lamps

ISO 16474-3, Paints and varnishes — Methods of exposure to laboratory light sources — Part 3: Fluorescent UV lamps

ISO 16474-4, Paints and varnishes — Methods of exposure to laboratory light sources — Part 4: Open-flame carbon-arc lamps

3 Terms and definitions

For the purposes of this document, the terms and definitions given in ISO 4618 and the following apply.