INTERNATIONAL STANDARD

First edition 2008-10-15

Metallic materials — Sheet and strip — Determination of forming-limit curves —

Part 2:

Determination of forming-limit curves in the laboratory

Matériaux métalliques — *Tôles et bandes* — *Détermination des courbes limites de formage* —

Partie 2: Détermination des courbes limites de formage en laboratoire



Reference number ISO 12004-2:2008(E)

PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below

This document is a preview denerated by Fig.



COPYRIGHT PROTECTED DOCUMENT

© ISO 2008

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office Case postale 56 • CH-1211 Geneva 20 Tel. + 41 22 749 01 11 Fax + 41 22 749 09 47 E-mail copyright@iso.org Web www.iso.org Published in Switzerland

Contents

Forewo	ord	iv
Introdu	uction	v
1	Scope	1
2	Symbols and abbreviated terms	1
3	Principle.	2
4	Test pieces and equipment	3
5	Analysis of strain profile and measurement of ε_1 - ε_2 pairs	10
6	Documentation	15
7	Test report	16
Annex	A (normative) Second derivative and "filtered" second derivative	17
Annex	B (normative) Calculation of the width of the fit window	18
Annex	C (normative) Evaluation of the inverse best-fit parabola on the "bell-shaped curve"	19
Annex	D (normative) Application/Measurement of grid — Evaluation with magnifying glass or microscope	21
Annex	E (informative) Tables of experimental at for validation of calculation programme	22
Annex	F (normative) Representation and mathematical description of FLC	23
Annex	G (informative) Examples of critical cross-sectional data	24
Annex	H (normative) Flowchart from measured strain distributions to FLC values	25
Bibliog	graphy	27
	H (normative) Flowchart from measured strain distributions to FLC values	

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in Maison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical convertues is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires applora by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for gentifying any or all such patent rights.

ISO 12004-2 was prepared by Technical Committee ISO/TC 164, Mechanical testing of metals, Subcommittee SC 2, Ductility testing.

This first edition of ISO 12004-2, together with ISO 12604-1, cancels and replaces ISO 12004:1997 which has been technically revised.

ISO 12004 consists of the following parts, under the general title Metallic materials — Sheet and strip — Determination of forming-limit curves:

Part 1: Measurement and application of forming-limit diagrams in the press shop tenerated by FLYs

Part 2: Determination of forming-limit curves in the laborator

Introduction

A forming-limit diagram (FLD) is a diagram containing major/minor strain points.

An FLD can distinguish between safe points and necked or failed points. The transition from safe to failed points is defined by the forming-limit curve (FLC).

To determine the forming limit of materials, two different methods are possible.

1) Strain analysis on failed press shop components to determine component and process dependent FLCs:

In the press shop, the strain paths followed to reach these points are generally not known. Such an FLC depends on the material, the component and the chosen forming conditions. This method is described in ISO 12004-1.

2) Determination of FLCs under well-defined laboratory conditions:

For evaluating formability, one unique FLC for each material in several strain states is necessary. The determination of the FLC has to be specific and it is necessary to use different linear strain paths. This method should be used for toperial characterization as described in ISO 12004-2.

For this part of ISO 12004 (concerning determination of forming-limit curves in laboratory), the following conditions are also valid.

- Forming-limit curves (FLCs) are determined for pecific materials to define the extent to which they can be deformed by drawing, stretching or any combination of drawing and stretching. This capability is limited by the occurrence of fracture, localized necking. Many methods exist to determine the forming limit of a material; however, it should be noted that results obtained using different methods cannot be used for comparison purposes.
- The FLC characterizes the deformation limit of a materia in the condition after a defined thermomechanical treatment and in the analysed thickness. For a judgement of formability, the additional knowledge of mechanical properties and the material's history for to the FLC-test are important.

To compare the formability of different materials, it is important not only ojudge the FLC but also the following parameters:

- a) mechanical properties at least in the main direction;
- b) percentage plastic extension at maximum force, according to ISO 6892-
- c) *r*-value with given deformation range, according to ISO 10113;
- d) *n*-value with given deformation range, according to ISO 10275.

this document is a preview denerated by EUS

Metallic materials — Sheet and strip — Determination of forming-limit curves —

Part 2: **Determination of forming-limit curves in the laboratory**

1 Scope

This part of ISO 12004 specifies the testing conditions to be used when constructing a forming-limit curve (FLC) at ambient temperature and using linear strain paths. The material considered is flat, metallic and of thickness between 0,3 mm and 4 mm.

NOTE The limitation in thickness of up to 4 mm is proposed, giving a maximum allowable thickness to the punch diameter ratio.

For steel sheet, a maximum thickness 52,5 mm is recommended.

2 Symbols and abbreviated terms

For the purposes of this document, the symbols and terms given in Table 1 apply.

0

Symbol	English	French	German	Unit
е	Engineering strain	Déformation conventionnelle	Technische Dehnung	%
ε	True strain (logarithmic strain)	Déformation vraie (déformation logarithmiqu	Wahre Dehnung (Umformgrad, Formänderung)	_
€ ₁	Major true strain	Déformation majeure vraie	Grössere Formänderung	
E2	Minor true strain	Déformation mineure vraie	Kleinere Formänderung	
E3	True thickness strain	Déformation vraie en épaisseur	Dickenformänderung	_
σ	Standard deviation	Ecart-type	Standardabweichung	_
D	Punch diameter	Diamètre du poinçon	Stempeldurchmesser	mm
D _{bh}	Carrier blank hole diameter	Diamètre du trou du contre-flan	Lochdurchmesser des Trägerblechs	mm
X(0), X(1) X(<i>m</i>)X(<i>n</i>)	X-position	Position en X	X-Position	mm
$f(x) = ax^2 + bx + c$	Best-fit parabola	Parabole de meilleur fit	Best-Fit-Parabel	
$f(x) = 1/(ax^2 + bx + c)$	Best-fit inverse parabola	Parabole inverse de meilleur fit	Inverse Best-Fit-Parabel	_

Table 1 — Symbols and abbreviated terms