



Corrigendum to CLC/TS 50238-2:2015

English version

In Table A.1, correct the frequency value for track circuit UGSK3 "222,45" with the correct value of "225,45" Hz to read:

"

UGSK 3	225,45	4	6,5	14	6	0,5		
--------	--------	---	-----	----	---	-----	--	--

"

July 2016