Eurocode 5: Design of timber structures

Part 2: Bridges

Estonian National Annex

Eurokoodeks 5: Puitkonstruktsioonide projekteerimine

Osa 2: Sillad

Eesti standardi rahvuslik lisa



FOREWORD

This document:

- is the Estonian National Annex to the European Standard EN 1995-2:2004 "Eurocode 5: Design of timber structures - Part 2: Bridges". It includes Estonian Nationally Determined Parameters (NDP) and procedures and it must be used together with EN 1995-2 for structural design of buildings and civil engineering works built in Estonia,
- was ratified with an order of Estonian Centre for Standardisation dated 16.11.2007 nr 167,
- is endorsed with the notification published in the December 2007 issue of the official bulletin of the Estonian Centre for Standardisation.

The National Annex of EVS-EN 1995-2 was prepared by a working group of TK 13 "Ehituskonstruktsioonide projekteerimine" supervised by Karl Õiger.

This document has been approved by Technical Committees EVS/TK 13 "Ehituskonstruktsioonide projekteerimine".

was iinistry

Particular of the struction in the structio The proposition to prepare a National Annex was made by EVS/TK 13, it was coordinated by the Estonian Centre for Standardisation and funded by the Ministry of Economic Affairs and Communications.

ICS 91.010.30 Technical aspects; 91.080.20 Timber structures; 93.040 Bridge construction Price group A

The right to reproduce and distribute standards belongs to the Estonian Centre for Standardisation

No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying, without a written permission from the Estonian Centre for Standardisation.

If you have any questions about standards copyright, please contact the Estonian Centre for Standardisation: Aru 10, 10317 Tallinn, Estonia; www.evs.ee; phone: 605 5050; e-mail: info@evs.ee

CONTENTS

CONTENTS	
NA.2.3.1.2 NA.2.4.1 NA.7.2 NA.7.3.1	Load-duration classes4Design value of material property4Limiting values for deflections5Vibrations caused by pedestrians5
To	
	6,
	9,