
**Optics and optical instruments — Optical
coatings —**

**Part 4:
Specific test methods**

Optique et instruments d'optique — Traitements optiques —

Partie 4: Méthodes d'essai spécifiques



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

This document is a preview generated by EVS

© ISO 2006

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword.....	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions.....	1
4 Test conditioning	1
5 Abrasion resistance tests (conditioning method 01: abrasion)	1
5.1 General.....	1
5.2 Test conditions	2
5.3 Degree of severity (conditioning method 01: abrasion)	2
5.4 Recovery.....	2
5.5 Evaluation.....	2
6 Adhesion tests (conditioning method 02: adhesion).....	3
6.1 General.....	3
6.2 Test conditions	3
6.3 Degree of severity (conditioning method 02: adhesion)	3
6.4 Recovery.....	3
6.5 Evaluation.....	3
7 Crosshatch test (conditioning method 03: crosshatch)	4
7.1 General.....	4
7.2 Test conditions	4
7.3 Conditioning.....	4
7.4 Recovery.....	4
7.5 Evaluation.....	4
8 Solubility tests (conditioning method 04: solubility).....	5
8.1 General.....	5
8.2 Test conditions	5
8.3 Degree of severity (conditioning method 04: solubility)	5
8.4 Recovery.....	6
8.5 Evaluation.....	6
9 Environmental test code	6
Annex A (normative) Materials for abrasion testing of optical coatings.....	7
Annex B (normative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings	10
Annex C (informative) Visual examination of optical coatings.....	12
Bibliography	13

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 9211-4 was prepared by Technical Committee ISO/TC 172, *Optics and photonics*, Subcommittee SC 3, *Optical materials and components*.

This second edition cancels and replaces the first edition (ISO 9211-4:1996), Clauses 4, 5, 6, and Table 3 and Annex A of which have been technically revised. A new Clause 6 and Table 3 have been added to this second edition. The original Clause 6 has been renumbered Clause 7 and the original Table 3 has been renumbered Table 4. A new normative Annex B has been added and the previous Annex B is now Annex C.

ISO 9211 consists of the following parts, under the general title *Optics and optical instruments — Optical coatings*:

- *Part 1: Definitions*
- *Part 2: Optical properties*
- *Part 3: Environmental durability*
- *Part 4: Specific test methods*

Optics and optical instruments — Optical coatings —

Part 4: Specific test methods

1 Scope

This part of ISO 9211 describes surface treatments of components and substrates excluding ophthalmic optics (spectacles) by the application of optical coatings, and gives a standard form for their specification. It defines the general characteristics and the test and measurement methods whenever necessary, but is not intended to define the process method.

This part of ISO 9211 describes specific test procedures for coating environmental durability tests that are identified in ISO 9211-3 but not described in other normative references.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 48, *Rubber, vulcanized or thermoplastic — Determination of hardness (hardness between 10 IRHD and 100 IRHD)*.

3 Terms and definitions

For the purposes of this document, the terms and definitions given in ISO 9211-1:1994 apply.

4 Test conditioning

Before and after subjecting a coated specimen (component or witness sample) to any inspection or test, the specimen shall be thoroughly cleaned as required to remove dirt, finger marks, smears, etc. Recommended storage time is at least 12 h after the coating process under ambient atmospheric conditions, or as specified between manufacturer and buyer.

5 Abrasion resistance tests (conditioning method 01: abrasion)

5.1 General

The purpose of these tests is to evaluate to what extent the optical and mechanical properties of optical coatings on components and substrates are affected when subjected to specific abrading conditions at ambient atmospheric conditions.