INTERNATIONAL STANDARD



Third edition 2016-07-15

Optics and photonics — Environmental test methods —

Part 1: Definitions, extent of testing

Optique et photonique — Méthodes d'essais d'environnement — Partie 1: Définitions, portée des essais



Reference number ISO 9022-1:2016(E)



© ISO 2016, Published in Switzerland

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office Ch. de Blandonnet 8 • CP 401 CH-1214 Vernier, Geneva, Switzerland Tel. +41 22 749 01 11 Fax +41 22 749 09 47 copyright@iso.org www.iso.org

Page

Contents

Fore	eword	iv
Intr	oduction	vi
1	Scope	
2	Terms and definitions	
3	Procedure 3.1 Test sequence 3.2 Preconditioning (specimen preparation) 3.3 Initial test 3.4 Conditioning 3.5 Intermediate test (in state of operation 2 only) 3.6 Recovery 3.7 Final test 3.8 Evaluation	3 3 3 3 3 3 3 3 3 3
4	Environmental test code	
Ann	ex A (informative) List of relevant parts of ISO 9022 and conditioning methods	
Bibl	iography	7
@ 150	2016 – All rights reserved	ii

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see <u>www.iso.org/directives</u>).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see <u>www.iso.org/patents</u>).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation on the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the WTO principles in the Technical Barriers to Trade (TBT) see the following URL: Foreword - Supplementary information

The committee responsible for this document is ISO/TC 172, *Optics and photonics*, Subcommittee SC 1, Fundamental standards.

This third edition cancels and replaces the second edition (ISO 9022-1:2012), which has been revised to reflect the changes made to the ISO 9022 series.

ISO 9022 consists of the following parts, under the general title Optics and photonics — Environmental ρ. Constant of the second sec *test methods*:

- Part 1: Definitions, extent of testing
- Part 2: Cold, heat and humidity
- Part 3: Mechanical stress
- Part 4: Salt mist
- Part 6: Dust
- Part 7: Resistance to drip or rain
- Part 8: High internal pressure, low internal pressure, immersion
- Part 9: Solar radiation and weathering
- Part 11: Mould growth
- Part 12: Contamination
- Part 14: Dew, hoarfrost, ice
- Part 17: Combined contamination, solar radiation
- Part 20: Humid atmosphere containing sulfur dioxide or hydrogen sulfide

- Part 22: Combined cold, dry heat or temperature change with bump or random vibration

Introduction

Optical instruments are affected during their use by a number of different environmental parameters which they are required to resist without significant reduction in performance and to remain within defined specifications.

The type and severity of these parameters depend on the conditions of use of the instrument (for example, in the laboratory or workshop) and on its geographical location. The environmental effects on optical instrument performance in tropical and subtropical climates are totally different from those found when they are used in the arctic regions. Individual parameters cause a variety of different and overlapping effects on instrument performance.

The manufacturer attempts to ensure, and the user naturally expects, that instruments will resist the likely rigours of their environment throughout their life. This expectation can be assessed by exposure of the instrument to a range of simulated environmental parameters under controlled laboratory conditions. The severity of these conditions is often increased to obtain meaningful results in a relatively short period of time.

In order to allow assessment and comparison of the response of optical instruments to appropriate environmental conditions, ISO 9022 contains details of a number of laboratory tests which reliably simulate a variety of different environments. The tests are based largely on IEC standards, modified where necessary to take into account features specific to optical instruments.

As a result of continuous progress in all fields, optical instruments are no longer only precisionengineered optical products, but depending on their range of application, also contain additional assemblies from other fields. For this reason, the principal function of the instrument is to be assessed to determine which International Standard should be used for testing. If the optical function is of primary importance, then ISO 9022 is applicable, but if other functions take precedence, then the appropriate International Standard in the field concerned should be applied. Cases may arise where application of both ISO 9022 and other appropriate International Standards will be necessary.

Optics and photonics — Environmental test methods —

Part 1: **Definitions, extent of testing**

1 Scope

This part of ISO 9022 defines terms relating to environmental tests of optical and photonic instruments, including additional assemblies from other fields (e.g. mechanical, chemical and electronic devices), and specifies basic features of testing.

2 Terms and definitions

For the purposes of this document, the following terms and definitions apply.

2.1

environmental test

laboratory simulation, usually severe, of the climatic, mechanical, biological, electrical (including electrostatic) and chemical environmental influences acting on the specimen during assembly, storage, transport and operation, in order to establish any changes in the behaviour of the specimen in a short time

2.2

optical instrument

photonic instrument

instrument whose function is mainly based on optical phenomena, consisting of several assemblies and/or components, illumination systems, instruments with light conduction and instruments which, apart from optical units, contain assemblies and/or components from other fields

EXAMPLE Electronic components.

2.3

optical assembly

functional unit consisting of several components, at least one of which has an optical function

2.4

component

<optical instrument> smallest unit, generally consisting of one piece and one material

2.5

representative sample

sample which differs from a component only in its geometry

EXAMPLE An optical part or piece of sheet metal.

2.6

specimen

instrument, assembly, component or representative sample which is being tested

2.7

test

procedure by which the effect of applied parameters on the properties of a specimen is determined and assessed